

PRODUCT DISCONTINUE NOTIFICATION 产品中止公告(PDN)

PDN No. : PDN 编号	PDN-16-001	Issued Date 发出日期:	2016-07-13
		Issued By 发行人:	Congcong Liu
Classification : 类别	End Of Life 产品结束	Approved By 批准人:	Manufacturing Manager: QA Manager: Sales & Marking Manager General Manager:

TITLE: Discontinue the Production of Quadro Mini-MELF Package

LAST BUY DATE: Oct. 15, 2016

LAST SHIP DATE: Oct 31, 2016

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Name : Gary Huang
Email : l.g.huang@takcheong.com
Direct Line : 86-660- 3281179

NOTIFICATION TYPE:

Product end of life

DESCRIPTION AND PURPOSE:

Tak Cheong decided to discontinue the production of Quadro Mini-MELF (LS34) products.

AFFECTED PRODUCT LIST:

See attached product list

POSSIBLE REPLACEMENT PART:

Standard LL34 package

PRODUCT DISCONTINUE NOTIFICATION

产品中止公告(PDN)

PDN No. : PDN-16-001
PDN 编号

Issued Date 发出日期: 2016-07-13

Issued By 发行人: Congcong Liu

Classification : End Of Life
类别 产品结束

Approved By 批准人: Manufacturing Manager:

QA Manager:

Sales & Marking Manager

General Manager:

AFFECTED PRODUCT LIST

Device	Package	Device	Package	Device	Package	Device	Package
TCLS4148	LS34	TCBZT55B 3V0	LS34	VLZ3V3B	LS34	VLZ15VA	LS34
TCLS4448	LS34	TCBZT55B 3V3	LS34	VLZ3V6A	LS34	VLZ15VB	LS34
TCLS914B	LS34	TCBZT55B 3V6	LS34	VLZ3V6B	LS34	VLZ15VC	LS34
TCBZT55C2V0	LS34	TCBZT55B 3V9	LS34	VLZ3V9A	LS34	VLZ16VA	LS34
TCBZT55C2V2	LS34	TCBZT55B 4V3	LS34	VLZ3V9B	LS34	VLZ16VB	LS34
TCBZT55C2V4	LS34	TCBZT55B 4V7	LS34	VLZ4V3A	LS34	VLZ16VC	LS34
TCBZT55C2V7	LS34	TCBZT55B 5V1	LS34	VLZ4V3B	LS34	VLZ18VA	LS34
TCBZT55C3V0	LS34	TCBZT55B 5V6	LS34	VLZ4V3C	LS34	VLZ18VB	LS34
TCBZT55C3V3	LS34	TCBZT55B 6V2	LS34	VLZ4V7A	LS34	VLZ18VC	LS34
TCBZT55C3V6	LS34	TCBZT55B 6V8	LS34	VLZ4V7B	LS34	VLZ20VA	LS34
TCBZT55C3V9	LS34	TCBZT55B 7V5	LS34	VLZ4V7C	LS34	VLZ20VB	LS34
TCBZT55C4V3	LS34	TCBZT55B 8V2	LS34	VLZ5V1A	LS34	VLZ20VC	LS34
TCBZT55C4V7	LS34	TCBZT55B 9V1	LS34	VLZ5V1B	LS34	VLZ20VD	LS34
TCBZT55C5V1	LS34	TCBZT55B 10	LS34	VLZ5V1C	LS34	VLZ22VA	LS34
TCBZT55C5V6	LS34	TCBZT55B 11	LS34	VLZ5V6A	LS34	VLZ22VB	LS34
TCBZT55C6V2	LS34	TCBZT55B 12	LS34	VLZ5V6B	LS34	VLZ22VC	LS34
TCBZT55C6V8	LS34	TCBZT55B 13	LS34	VLZ5V6C	LS34	VLZ22VD	LS34
TCBZT55C7V5	LS34	TCBZT55B 15	LS34	VLZ6V2A	LS34	VLZ24VA	LS34
TCBZT55C8V2	LS34	TCBZT55B 16	LS34	VLZ6V2B	LS34	VLZ24VB	LS34
TCBZT55C9V1	LS34	TCBZT55B 18	LS34	VLZ6V2C	LS34	VLZ24VC	LS34
TCBZT55C10	LS34	TCBZT55B 20	LS34	VLZ6V8A	LS34	VLZ24VD	LS34
TCBZT55C11	LS34	TCBZT55B 22	LS34	VLZ6V8B	LS34	VLZ27VA	LS34
TCBZT55C12	LS34	TCBZT55B 24	LS34	VLZ6V8C	LS34	VLZ27VB	LS34
TCBZT55C13	LS34	TCBZT55B 27	LS34	VLZ7V5A	LS34	VLZ27VC	LS34
TCBZT55C15	LS34	TCBZT55B 30	LS34	VLZ7V5B	LS34	VLZ27VD	LS34
TCBZT55C16	LS34	TCBZT55B 33	LS34	VLZ7V5C	LS34	VLZ30VA	LS34
TCBZT55C18	LS34	TCBZT55B 36	LS34	VLZ8V2A	LS34	VLZ30VB	LS34
TCBZT55C 20	LS34	TCBZT55B 39	LS34	VLZ8V2B	LS34	VLZ30VC	LS34
TCBZT55C 22	LS34	TCBZT55B 43	LS34	VLZ8V2C	LS34	VLZ30VD	LS34
TCBZT55C 24	LS34	TCBZT55B 47	LS34	VLZ9V1A	LS34	VLZ33VA	LS34
TCBZT55C 27	LS34	TCBZT55B 51	LS34	VLZ9V1B	LS34	VLZ33VB	LS34
TCBZT55C 30	LS34	TCBZT55B 56	LS34	VLZ9V1C	LS34	VLZ33VC	LS34
TCBZT55C 33	LS34	TCBZT55B 62	LS34	VLZ10VA	LS34	VLZ33VD	LS34
TCBZT55C 36	LS34	TCBZT55B 68	LS34	VLZ10VB	LS34	VLZ36VA	LS34
TCBZT55C 39	LS34	TCBZT55B 75	LS34	VLZ10VC	LS34	VLZ36VB	LS34
TCBZT55C 43	LS34	VLZ2V2A	LS34	VLZ11VA	LS34	VLZ36VC	LS34
TCBZT55C 47	LS34	VLZ2V2B	LS34	VLZ11VB	LS34	VLZ36VD	LS34
TCBZT55C 51	LS34	VLZ2V4A	LS34	VLZ11VC	LS34	VLZ39VA	LS34
TCBZT55C 56	LS34	VLZ2V4B	LS34	VLZ12VA	LS34	VLZ39VB	LS34
TCBZT55C 62	LS34	VLZ2V7A	LS34	VLZ12VB	LS34	VLZ39VC	LS34
TCBZT55C 68	LS34	VLZ2V7B	LS34	VLZ12VC	LS34	VLZ39VD	LS34
TCBZT55C 75	LS34	VLZ3V0A	LS34	VLZ13VA	LS34		
TCBZT55B 2V4	LS34	VLZ3V0B	LS34	VLZ13VB	LS34		
TCBZT55B 2V7	LS34	VLZ3V3A	LS34	VLZ13VC	LS34		